Network #'s: 192.168.0.4: scanner, .5 camera, .1 computer

2010 YUBA RIVER / DAGUERRE / SOUTH FISH LADDER LOG

Axis password: Root Vaki

date	arrival time	staff on site	system status (off/on)	battery voltage	solar output	weather (Clr, Cldy, Rain)	data download (Y/N)	system reset (Y/N)	debris load (Lt, mod, Hvy)	debris removed (Y/N)	swim in ladder (Y/N)	up/down counts	time of disconnect	time of reconnect	time of departure	comments
8/13	1303	DG	OFF	12.2	0.0	CLR	N	N	LT	N	N	—	—	—	1347	computer still not operational,
8-16	0900	RH NI	off	13.9	6.7	CLR	N	N	LT	Y	Y				1045	Full cleaning. 3 ctn seen ascending on arrival.
Oper	gate	valve	slightly	to	accomodate	future	drops	in	Fish	Ladder						
8-19	0900	RH CC	off	13.0	0.0	CLR	N	N	LT	Y	Y	N/A			1500	install new multiplexer, PC. Cant get connected. Left off
carcass	laying	next	to	top	pool	by	dam	(?).	Put	in	ladder.					
8-23	0930	RH KT	off	13.2	8.3	CLR	N	N	LT	Y	Y	N/A	X	X	1230	Run cat 6 cable direct to multipleter. Run Cat 6
straight	to	camera.	JV	Fuse.	Remove	dead	multiplexer	and	take	to	North	to	test.	not	operating.	
8-25	0900	RH CP	off	13.2	0.0	CLR	N	N	LT	Y	Y	N/A	X	Y	1240	cut extra Ladder Boards, ADD Board to step 3.
steps	numbered	1-5	From	Bottom	of	ladder.	Labeled	boards.	Open	Gate	valve	completely.				
8-31	1400	RH CL DM	off	13.5	7.0	CLR	N	N	LT	Y	Y	X	X	1630	1635	Moricom will not match up ip for video. Install
DD series	converter.	Power	is	sent	to	Moricom	successfully.	Scanners	work.	Lights	work	But	f.	Ladder	closed	1400-1630
9-1	857	RH KT	ON	13.5	9.3	CLR	N	N	LT	N	N	1/0	902	1015	1015	Troubleshoot camera non-op, not working
9-2	904	RH KT CL	ON	13.4	9.8	CLR	N	N	LT	Y	Y	10/0	904	1208	1245	Axis cameras swapped. North camera connects + works
Find	on	south	side	South	camera	does	not	work	on	North.	Leave	up	out	camera	installed.	Gate valve closed during work.
9-7	855	RH KT	ON	13.4	9.5	CLR	Y	Y	LT	N	N	35/0	856	858	900	No video. Sent download folder to desktop under "South Vaki 2010"
9-8	1000	RH KT	ON	13.0	7.0	CLDY	N	N	LT	Y	Y	5/0	1003	1245	1310	all systems go. camera wiring Final problem solved. Switch green
with	Black	(power)	inside	camera	housing.	Ladder	closed	while	working.							
9/9	08:48	KT	on	13.5	8.6	clear	N	N	LT	N	N	12/1	N/A	N/A	08:53	Came up while fishing/Acusing Taggins- 2 up today 0 ↓
9-13	0740	RH KT	ON	12.6	1.5	CLR	Y	Y	LT	N	N	32/1	0746		0815	close dam 0750. Culvert work starts ~0630. Water murky.
Tracy	on	site	to	test	turbidity.	Water	returning	water	to	open.	ADD	date	+	time	stamp	to images in AXIS setup.
9/13	13:41	KT	off	13.5	13.9	clear	N	N	LT	N	N	0/0	N/A	13:49		Came back to restart Comp/V on ladder mouth after Army Core
9-14	1545	RH VT	ON	13.5	10.6	CLR	N	N	LT	N	N	132/0	N/A	n/a	1615	Stopped it back up after work on culvert.
Unload	on	USACE	work	on	culvert.	2	Kofter	dams	installed	on	portage.	some	debris	removed	from	opening (by RH KT)
9/17	H17	DG	ON	13.6	7.6	CLDY	N	N	LT	N	N	143/0	N/A	N/A	1422	good
9-20	1430	RH KT BN	ON	13.5	13.0	CLR	Y	Y	MOD	Y	Y	156/0	1430	1432	1530	culvert work continues above dam.
9-21	840	RH JR	ON	13.2	9.3	CLR	N	N	LT	N	N	1/0	X	X	845	
9-27	1533	RH CC	ON	13.4	10.3	CLR	Y	Y	MOD	Y	Y	78/29	1534	1537	1545	. Full cleaning. Lots of sunken large stick/logs. 1 ctn carcass on grate
10-4	820	RH KT	ON	12.5	1.2	CLDY	Y	Y	LT	Y	N	82/4	822	825	850	Rain forecasted.
10-7	930	RH LA	ON	12.7	3.6	CLDY	N	N	LT	N	N	63/5	X	X	935	Carcass on Vaki Grate again (?)
10-13	1715	RH KT	ON	13.3	.9	CLR	Y	Y	MOD	N	N	163/8	1716	1721	1730	Beaver activity some Front Clog
10-14	812	RH KT BN	ON	12.8	6.4	CLR	N	N	MOD	Y	Y	6/2	815	907	930	Full cleaning. major Beaver Blockage.
10/18	08:42	KT/BN	ON	12.8	1.9	CLR	N	N	LT	Y	N	99/5	N/A	N/A	09:07	Beaver activity again, Front mouth, ladder was clear
10-21	0840	RH JR	ON	13.0	8.9	CLR	Y	Y	LT	N	N	196/4	844	848	855	2 ctn in top pool, 2 carcass on bank next to top pool
10-25	1120	RH	ON	13.3	2.2	P.CLDY	Y	Y	MOD	Y	Y	413/13	1126	1248	1300	Beaver charging again, bad. Removed most but not all. 1 carcass next to top pool
Full	cleaning	and	brush	stump	to	weir	+	Bars.	Remove	some	files	from	USB	Portable	drive	to make room for New Data (card Full)

updated 2/2010